



REVISIONS

KRAMER
TRENTON N.J.

SCHEMATIC WIRING DIAGRAM FOR
C-12L COMPRESSOR UNIT
230-3-60 MAIN, 230-1-60 CONTROLS
SCALE: ——— DWG. No. A-21568-11-W

- NOTES:**
1. ALL WIRING SHOWN IN DOTTED LINES - BY INSTALLER.
 2. ALL SINGLE PHASE MOTORS HAVE BUILT-IN OVERLOAD PROTECTION.
 3. REMOTE CONDENSERS REQUIRE FIELD WIRING.
 4. ONE THERMOSTAT IS SUPPLIED FOR EACH EVAPORATOR WHERE TWO OR MORE EVAPORATORS ARE SUPPLIED FOR ONE SYSTEM THE DEFROST THERMOSTATS SHOULD BE ELECTRICALLY CONNECTED IN SERIES.
 5. FOR LADDER DIAGRAM SEE A-21568-10-LD.

DRAWN BY	DATE	CHECKED	APPROVED
O.W / R.N.B.	4-15-69		

WIRING FOR IMMERSION HEATER

CHECK YOUR THERMOBANK FOR AN IMMERSION HEATER. IF AN IMMERSION HEATER IS SCREWED INTO THE THERMOBANK, IT MUST BE WIRED TO A FUSED BRANCH CIRCUIT AS FOLLOWS:

IMMERSION HEATER (SEE INSTALLATION INSTRUCTIONS FOR IMMERSION HEATER) (BY INSTALLER)

LINE VOLTAGE

CONNECTING WIRING - BY INSTALLER